



Blue Canyon Pool & Spa

Sales – Service – Repairs

Actual Clients' Tests with Before & After Results

Yorba Linda Customer:

Test	Before	After
<i>Free Chlorine</i>	1.0	0.5
<i>Combined Chlorine</i>	1.0	0
<i>Ph</i>	7.4	7.0
<i>Total Alkalinity</i>	130	60
<i>Calcium Hardness</i>	1400	200
<i>CYA</i>	40	0
<i>Total Dissolved Solids</i>	6000	778
<i>Salinity</i>	4,400	490

Lakewood Customer:

Test	Before	After
<i>Free Chlorine</i>	1	0
<i>Combined Chlorine</i>	1	0
<i>Ph</i>	7.8	7.4
<i>Total Alkalinity</i>	100	70
<i>Calcium Hardness</i>	1750	150
<i>CYA</i>	0	0
<i>Total Dissolved Solids</i>	7435	402
<i>Salinity</i>	4901	242

Sierra Madre Customer

Test	Before	After
<i>Free Chlorine</i>	16	0
<i>Combined Chlorine</i>	1.5	0.5
<i>Ph</i>	7.0	7.0
<i>Total Alkalinity</i>	170	60
<i>Calcium Hardness</i>	2560	150
<i>CYA</i>	300+	50
<i>Total Dissolved Solids</i>	4435	317
<i>Salinity</i>	442	152



Actual Clients' Tests with Before & After Results

Yorba Linda Customer:

Test	Before	After
<i>Free Chlorine</i>	1.4	1.0
<i>Combined Chlorine</i>	0.2	0.5
<i>Ph</i>	8.0	7.3
<i>Total Alkalinity</i>	130	80
<i>Calcium Hardness</i>	650	100
<i>CYA</i>	60	0
<i>Total Dissolved Solids</i>	4220	402
<i>Salinity</i>	3560	290

Trabuco Canyon Customer:

Test	Before	After
<i>Free Chlorine</i>	2	0
<i>Combined Chlorine</i>	.5	0
<i>Ph</i>	7.4	7.0
<i>Total Alkalinity</i>	7.0	50
<i>Calcium Hardness</i>	1,100	100
<i>CYA</i>	55	0
<i>Total Dissolved Solids</i>	6,304	385
<i>Salinity</i>	4,926	265

Fountain Valley Customer:

Test	Before	After
<i>Free Chlorine</i>	2	0
<i>Combined Chlorine</i>	4	0
<i>Ph</i>	7.7	7.2
<i>Total Alkalinity</i>	60	70
<i>Calcium Hardness</i>	2275	120
<i>CYA</i>	50	0
<i>Total Dissolved Solids</i>	9563	730
<i>Salinity</i>	6249	524



Actual Clients' Tests with Before & After Results

Mission Viejo Customer:

Test	Before	After
<i>Free Chlorine</i>	1.0	0
<i>Combined Chlorine</i>	0	0
<i>Ph</i>	8.0	7.4
<i>Total Alkalinity</i>	160	60
<i>Calcium Hardness</i>	1,500	130
<i>CYA</i>	300	0
<i>Total Dissolved Solids</i>	3,255	331
<i>Salinity</i>	1,650	190

Riverside Customer:

Test	Before	After
<i>Free Chlorine</i>	40+	0
<i>Combined Chlorine</i>	-	0
<i>Ph</i>	7.4	6.7
<i>Total Alkalinity</i>	100	60
<i>Calcium Hardness</i>	1475	140
<i>Total Dissolved Solids</i>	6992	655
<i>Salinity</i>	4600	467

Yorba Linda Customer:

Test	Before	After
<i>Free Chlorine</i>	2.5	0
<i>Combined Chlorine</i>	0	0
<i>Ph</i>	8.0	7.4
<i>Total Alkalinity</i>	140	100
<i>Calcium Hardness</i>	750	100
<i>CYA</i>	60	0
<i>Total Dissolved Solids</i>	5562	789



Blue Canyon Pool & Spa

Sales – Service – Repairs

Salinity

4763

676

Actual Clients' Tests with Before & After Results

Yorba Linda Customer:

Test	Before	After
<i>Free Chlorine</i>	0.5	0
<i>Combined Chlorine</i>	1.0	0.5
<i>Ph</i>	8.0	7.0
<i>Total Alkalinity</i>	200	70
<i>Calcium Hardness</i>	1000	100
<i>CYA</i>	30	0
<i>Total Dissolved Solids</i>	5762	590
<i>Salinity</i>	4620	384